

November 30, 2018

## **St Mary's Glacier Water and Sanitation District Operations Report**

**Prepared by –** Michelangelo Creazzo and Gabrielle Begeman

### **WTP's**

#### **Well 1**

- Well #1 is in good operational condition. Only need at this point is a new flow meter or the part to fix it. The part is the output module which is 1000.00 and would require a specialist to calibrate flow meter or a new flow meter which is a about 5000.00. Could this be part of capital improvements?

#### **Well 5**

- Rebuilt Sodium Hydroxide pump as it was leaking.

### **Distribution System**

- Alice boodter work on VFD still continues. Might have a bad wire which is causing the problem. Found 2 loose wire but this did not fix it.
- Did the Lead pipe survey for homes 1940 and older. Most of these homes are not lived in. 2 homes were and both home have had there lead lines replaced.
- Completed the Lead and copper sampling and updated the CDPHE porthole. All sites are Tier 1.
- 

### **Collections System**

- 

### **WWTP**

- Called Excel energy out to see if power is good coming into plant as the Blower motor keeps tripping. Power was good. They are sending out a specialist to install a monitor to compile data on why the motor is tripping
- Ordered the new motor for the Blower.